


ScanCast™ Action Barcodes:


For Model # [MC020085] Large (3x3)




Reset



Enable ^[1]



Disable



Continue

[1] Default settings after power on.

[2] These settings are Non-volatile and will be retained across power cycles.

ScanCast™ Action Barcodes:


For Model # [MC020085] Large (3x3)




Intentionally left blank.

ScanCast™ Action Barcodes:


For Model # [MC020085] Large (3x3)




Archive And Close



Send To Queue



Skip Shelf



Line Ending: None ^[2]

[1] Default settings after power on.

[2] These settings are Non-volatile and will be retained across power cycles.

ScanCast™ Action Barcodes:


For Model # [MC020085] Large (3x3)




Intentionally left blank.

ScanCast™ Action Barcodes:


For Model # [MC020085] Large (3x3)



Line Ending: LF ^[2]



Line Ending: CR ^[2]



Line Ending: LF+CR ^[2]

[1] Default settings after power on.

[2] These settings are Non-volatile and will be retained across power cycles.

ScanCast™ Action Barcodes:

For Model # [MC020085] Large (3x3)



Intentionally left blank.